SIEMENS

MOBILETT Plus

RX

Exchanging the lower arm friction adjustment screw

Repair Instructions

RX R8-215-091.01.01.02

English
01.96

Weitergabe sowie Vervielfältigung dieser Unterlage, Verwertung und Mittelung ihres Inhalts nicht gestattet, soweit nicht ausdrücklich zugestanden. Zuwiderhandlungen verpflichten zu Schadenersatz. Alle Rechte für den Fall der Patenterteilung oder GM-Eintragung vorbehalten.

Propriety data, company confidential. All rights reserved.
Confié a titre de secret d´enterprise. Tous droits réservés.
Confiado corno secreto industrial. Nos reservamos todos los derechos.

63 98 585

1 - 2 Exchanging the lower arm friction adjustment screw

Document required

- Service Instructions, RX R8-215-061.01.....

Tool required

- Tool kit for technicians
- Tap drill for M6

Components required

- Spare part kit 63 70 444

Time required

- 0,5h

For Safety requirements and general service instructions see Service Instructions, applicable parts of section 4.8 - Replace the friction linings.

Procedure:

- Dismount the existing screw.
- Drill through the aluminium bar with an M6 tap to ensure the clearance of the new screw.
- ***Remove metal chips from the unit.***
- Install the new, longer screw with washers. Adjust until the lower arm stands still in any position. Lock with the nut.